

STD \$\$ PARENT	COMPONENT DESCRIPTION	STD \$\$	QTY	TOTAL
-----------------	-----------------------	----------	-----	-------

GVP BOM AS OF NOV 20. 1993 BASED ON STANDARD COST

22.83	100503	SHIP ASSY, A1291 SCSI	22.83	TOTAL	
	415018-02	PC ASSY, A1291 R2.00	19.26		
		BARE BOARD		2.850	
		PASSIVE		1.164	
		LOGIC		3.340	
		AMD 33CDPRC		6.000	
		SOCK/CONN		0.500	
		OTHER		1.060	
		SUB LABOR		4.500	
		DOC PKG LESS LABOR	1.62		
		GVP LABOR	0.85		
		OTHER	1.103		
22.83	100503				
	100503	300027	DOC PKG, A1230II SCSI	1.792	1.0 1.79
	100503	415018-02	PC ASSY, A1291 R2.00	19.256	1.0 19.26
	100503	910004	SCREW, PHMS, 6-32 X 3/8	0.003	1.0 0.00
	100503	930015	BAG, ANTISTATIC 4x6	0.070	1.0 0.07
	100503	931024	FOAM CROSS, A1200 SERIES	0.650	1.0 0.65
	100503	940056	BOX, SLEEVE A1291	0.510	1.0 0.51
	100503	941008	LABEL, BAG, ANTISTATIC CAUTION	0.020	1.0 0.02
	100503	941139	LABEL, BLANK BAR CODE BOX	0.020	1.0 0.02
	100503	941140	LABEL, BLANK BAR CODE SERIAL	0.008	1.0 0.01
	100503	999998	GVP LABOR	0.250	2.0 0.50
1.79	300027				
	300027	920042	MANUAL, INST A1200II SCSI KIT	0.930	1.0 0.93
	300027	921001	CARD, WARRANTY, GENERIC	0.040	1.0 0.04
	300027	921003	CARD, SFTWR LICENSE	0.026	1.0 0.03
	300027	930013	BAG, POLY 7x10 ZIPLOCK W/HOLE	0.056	1.0 0.06
	300027	961055	DISK PROG, A1291 INSTALL v1.00	0.490	1.0 0.49
	300027	999998	GVP LABOR	0.250	1.0 0.25
19.26	415018-02				
	415018-02	500055-02	PCB, A1291 SCSI CNTRLR R2.00	2.850	1.0 2.85
	415018-02	510039	BRACKET, A1291	0.800	1.0 0.80
	415018-02	620042	IC, TL2218 TSSOP 20 PIN	1.670	2.0 3.34
	415018-02	630100	IC, 33C93A, PLCC44	6.000	1.0 6.00
	415018-02	680011-01	DIODE, 1N4001, SOD 80	0.050	1.0 0.05
	415018-02	711103	RES, 220 OHM, CHIP, 0805	0.007	2.0 0.01
	415018-02	711112	RES, 1K OHM, CHIP, 0805	0.007	1.0 0.01
	415018-02	721123	CAP, .22UF SMT0805	0.038	3.0 0.11
	415018-02	786003	FUSE, 700MA RADIAL LEAD SELFHL	0.980	1.0 0.98
	415018-02	911002	NUT, 6-32	0.103	1.0 0.10
	415018-02	950007	CONN, DB25, FEMALE RT>, PC **	0.360	1.0 0.36
	415018-02	950047	JUMPER, 2 PIN 2MM	0.040	2.0 0.08
	415018-02	951010	HDR, 2 PIN SIL 2MM BRKAW	0.030	2.0 0.06
	415018-02	999999	SUBCONTRACT LABOR	0.354	12.7 4.50
0.49	961055				
	961055	941180	LABEL, DISK A1291 SCSI INST	0.070	1.0 0.07
	961055	960001	DISK, BLANK	0.320	1.0 0.32
	961055	997051	DISK, MSTR A1291 INSTALL V1.00	0.000	1.0 0.00
	961055	999998	GVP LABOR	0.250	0.4 0.10

**this document was generously
contributed by
robert miranda**

**scanned by:
commodore international historical society
www.commodore.international**